



### Right Side Assembly

Notes:

- 1) All views shown are for left side assemblies unless otherwise noted.
- 2) Do not tighten Items 4 and 5 to the point where Item 3 deforms.  
It is acceptable if hardware is loose in the holes.



### Field Configuration



Folded Configuration

PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	TE-10001	Rear Ramp Assembly
2	1	GE-10033	Front Ramp Assembly
3	1	GE-10054	Handle, Ramp Assembly
4	2	HW-00002	Nut, Lock 1/4-20
5	2	HW-00046	1/4-20 x 1.25" Hex Head Bolt, Zinc Plated

DRAWN dfoster		11/29/2009		<b><i>FIRST</i></b> 200 Bedford Street, Manchester, NH 03101 (603) 666-3906 -- FAX (603) 666-3907	
CHECKED mcyrr		12/11/2009			
UNLESS OTHERWISE SPECIFIED <i>TOLERANCES: (INCHES)</i>					
FRAC.		+/- 1/32			
.00		+/- .01		TITLE <b>Ramp Assembly</b>	
.000		+/- .005			
ANGULAR		+/- .25 Deg.			
		SIZE <b>C</b>		DWG NO <b>TE-10003</b>	REV
		SCALE		SHEET 1 OF 1	